MITSUBISHI MOTOR SALES OF AMERICA, Inc.

TECHNICAL SERVICE BULLETIN

SUBJECT:
MONTERO DISTRIBUTOR — SERVICE MANUAL UPDATE

NO.	TSB-89-16-007
DATE	December, 1989
MODEL	1989 Montero

TSB Revision: TSB-89-16-007

PURPOSE

This bulletin is issued to correct an illustration in the 1989 Montero Service Manual. As reference to this bulletin, please write the TSB number in the revision box at the bottom of Page 8-159, and mark-up the illustration as shown below.

IGNITION SYSTEM – Distributor <2.6L Engine> 8-159



13. REMOVAL OF SPRING RETAINER/14. GOVERNOR SPRING

Remove two spring retainers with pliers and then remove two governor springs.

016987

FILE UNDER: Group 16 Engine Electrical in the Dealer Service Information Binder (728)

CIRCULATE TO:			
☐ GENERAL MANAGER	☐ PARTS MANAGER	☑ TECHNICIAN	☐ SERVICE ADVISOR
☑ SERVICE MANAGER	☐ WARRANTY PROCESSOR	☐ SALES MANAGER	